

**ROADS AND BUILDINGS DEPARTMENT
GOVERNMENT OF ANDHRA PRADESH**

From,
Sri. Y.V.Kishore Babuji. B.Tech.
Executive Engineer (R&B)
(R&B) Division, Eluru

To,
The Principal,
VIGNAN'S World one School,
R.S No.236/1237/1 240,241/12&245,
Bhogapuram (V) Pedavigi (M),
Eluru District.

Lr.No:-259/Soundness Certificate/JTO1/2020, Dt.28/ 10 / 2023.

Sir,

Sub:- (R&B) Division, Eluru VIGNAN'S World one School R.S.No.236/1,
237/1,240,241/1,2&245,Bhogapuram(V)Pedavegi (M) in Eluru
District - Soundness - Certificate - Issued-Reg.

Ref:- Request regarding the Soundness Certificate of Correspondent "VIGNAN'S
World one School R.S.No.236/1,237/1,240,241/1,2&245,Bhogapuram(V)Pedavegi
(M) in Eluru District, Dt: 05.10.2023 .

With reference to above, it is informed that the RCC Roofed building of
"VIGNAN'S World School R.S.No.236/1,237/1,240,241/1,2&245,Bhogapuram (V) Pedavegi
(M) in Eluru District is structurally sound to run the classes for a period of one year i.e. for
17.10.2023 to 16.10.2024.

Enclose: Soundness Certificate

Yours faithfully,


Executive Engineer (R&B)
(R&B) Division, Eluru

28/10/23


SOUNDNESS CERTIFICATE


Name of the School & Address	:	VIGNAN'S World one School, R.S.No.236/1,237/1,240,241/1,2 & 245 Bhogapuram (v), Pedavegi (M) Eluru District. Eluru
Name of the Mangement and phone number	:	Ph: 9052285339 E-Mail: vignanelur@gmail.com
Date of Inspection	:	A.E.E: 17-10-23
		D.E.E: 17-10-2023
1 Year of construction	:	2011
2 Type of the building	:	RCC Roof building (G.F+F.F+S.F)
3 Type of foundation footings, Basement and Plinth beam etc	:	Column Footing
4 Present condition of foundation whether any settlement cracks are observed upto basement level	:	Sound
5 Soundness of superstructure whether any cracks out of plumb in walls noticed	:	Sound
6 Soundness of RCC beam and lintels over openings	:	Sound
7 Condition of flooring	:	Sound
8 Condition of roof slabs, staircase slabs, cracks, leakages	:	Sound
9 Any other remarks which are required to ensure the structural soundness	:	This inspection certificate does not purport covering all the aspects of the work & designs .
10 Valid up to	:	16-10-2024

CERTIFICATE :

- 1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in future.
- 2) Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students. (such as cyclones severe weather conditions, Tsunamis, earth quakes etc.).
- 3) Department is not responsible for any strutral changes to the building in future course of time.

I do here by certify that I have inspected the school and found to structurally sound for running the School as the building is fit for the purpose of providing shelter from sun and rain.


Asst. Executive Engineer
(R&B) Section, Pedapadu.


Deputy Executive Engineer
(R&B) No.II, Sub-division, Eluru.

"Counter Signed"


Executive Engineer
(R&B) Division, ELURU

Asst.
28/10/23